

HOBIT Technical Memo No. 1

SUBJECT: Servicing the Witt Oxygen Blender (Monoplace)

Issue Date: 12/3/18



MEMO: Oxygen Blender Service

If needed / required; the Witt Oxygen Blender which is connected to the Magellan Ventilator MedGas manifold system, can be serviced through the Witt Company.

Witt Company contact information:



/ TECHNOLOGY FOR GASES /

Witt Gas Controls | 3080 Northfield Place Suite 111 | Roswell, GA. 30076 | USA

Phone 770-664-4447 | FAX 770-664-4448

witt-usa@wittgas.com | www.wittgas.us

Steps for returning blender to the Witt Company for service.

1. Customers must provide the blender's serial number along with an explanation of service request/issue.
2. A RMA number must be issued from Witt prior to returning the blender to Witt.
3. There is a \$100.00 non-refundable evaluation fee on any unit returned to the Witt Company for service which is payable in advance.
4. Customer pays all freight charges, incoming and outgoing.

NOTE: Recommend requesting an estimate for total repair charges.

HOBIT Technical Memo No. 1

SUBJECT: Servicing the Witt Oxygen Blender (Monoplace)

Issue Date: 12/3/18



PHOTO NO. 1 - WITT OXYGEN BLENDER

Please contact me with any concerns or questions.

Thank you,

Bill Gossett CHT, RRT

Director of Hyperbaric Technical Operations

HOBIT Trial | HennepinHealthcare Research Institute

HennepinHealthcare

701 Park Avenue | Minneapolis, MN 55415

Direct: 612-873-3961 | Cell: 612-868-1254

bill.gossett@hcmcd.org | hcmc.org

